

# FIRMWARE UPGRADE NOTICE : UEBO S400 V1.1.1

## 1、 Introduction

UEBO has released Version 1.1.1 of S400 firmware. This notice is to inform user of the changes.

## 2、 Impacted Product

<b>Product Involved</b>	UEBO S400
<b>Related Software</b>	S400_SysOS、 UEBO Finder

## 3、 Improvement Made

#	Improvement and Description
1	Added 802.11n USB Adapter support for TP-Link Model TL-WN821N
2	Improve on BT usability: 1) Added upload and download speed setting. 2) Change the design such that uploading doesn't start automatically after downloading is completed. 3) Resolved the issue where downloaded file cannot be edited or deleted. 4) Resolved the issue where download stops without warning.
3	Improve on compatibility with MAC OS 10.6.4: 1) Added Apple Time Machine support. 2) Enhance User authentication and Right management. 3) Enhance AFP share file transfer speed.
4	Enhance Web Manager interface to make it more user friendly.
5	Resolve issues with Office 2003 and AUTOCAD files saving.
6	Data preservation for NAS share after system upgrade.

## 4、 Known Problem

#	Description
1	The user needs to restart CIFS and AFP services after changing the System Name while connecting to CIFS and AFP volume.

2	Changing System Name while BT is downloading file will cause BT service to fail.
3	When using DHCP on one Ethernet port and fixed IP address on the other Ethernet port, the one using the fixed IP address cannot have Gateway address defined. Doing so will cause UEBO S400 to have two gateway addresses and cause networking issue.
4	After upgrading the System OS or installing the new System OS, the BT seed file will be lost. Please make sure to back up those seed files before upgrading or installing new System OS.